Oil Field Environmental Incident Summary

Responsible Party: CONTINENTAL RESOURCES, INC. **Well Operator:** CONTINENTAL RESOURCES, INC.

Well Name: WINKLER 1-3H

Field Name: BORDER Well File #: 21628

Date Incident:10/9/2015Time Incident:16:00Facility ID Number:County:BURKETwp:161Rng:94Sec:3Qtr.

Location Description:

Submitted By: Timothy Ilse Received By:

Contact Person: John Breding

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Treater Leak

Release Contained in Dike: Yes - Within Dike Reported to NRC: No

	Spilled	Units	Recovered	Units	
Oil	1	Barrels	1	Barrels	
Rrino	2	Rarrole	2	Rarrole	

Other

Description of Other Released Contaminant:

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

None

Areal Extent:

Followup Units

Potential Environmental Impacts:

Well site soil

Action Taken or Planned:

Contaminated material will be removed and replaced with clean-fill.

Wastes Disposal Location: R360

Agencies Involved:

Updates

Date: 10/12/2015 Status: Reviewed - Assigned to Other Agency Author: O'Gorman, Brian

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to a treater leak, remained within diking according to the report. NDIC retains oversight.